

FORM B - BUILDING


MASSACHUSETTS HISTORICAL COMMISSION
Office of the Secretary, State House, Boston

In Area no.	Form no.
B	73



Lexington
 7 Bedford Street
 Amos Muzzey House
 (Burr + Chittenden Clockmaking
 Worker Housing)
 Present use Dwelling
 Present owner Mae Curtis (occupant & owner?)
 Description: Early 1800's C1820
 Source Federal

4. Map. Draw sketch of building location in relation to nearest cross streets and other buildings. Indicate north.



DO NOT WRITE IN THIS SPACE
 USGS Quadrant _____
 MHC Photo no. _____

Architect _____
 Exterior wall fabric white clapboard
 Outbuildings (describe) tiny metal tool shed, two chimneys, gable roof-single side chimney rear
 Other features 5 over 4-overhang corner board granite block foundation-small portico-square tuscan engaged columns in doorway-sidelights
 On doorway
 Altered Addition on right Date _____
 side-gable dormer
 Moved _____ Date _____

5. Lot size:
 Less than one acre x Over one acre _____
 Approximate frontage 47'
 Approximate distance of building from street 11'

6. Recorded by Ruth Beebe
 Organization Lex. Hist. Com.
 Date Aug. 27. 1975